



Automatic Signal Wiring




12v dc
-
+



Mount 110v socket on an angle iron post or set in the ground.

Continuity Bonds across fishplates

Section Break



Block Length